





# Claude Allouez Bridge Condition Summary



**Aerial View of the Existing Bridge**

NATIONAL BRIDGE INSPECTION (NBI) RATING SCALE	
Score	Description
9	Excellent Condition
8	Very Good Condition
7	Good Condition
6	Satisfactory Condition
5	Fair Condition
4	Poor Condition
3	<b>Serious Condition</b> – Local Failures are possible
2	<b>Critical Condition</b> – May be necessary to close the bridge until corrective action is taken
1	<b>“Imminent” Failure Condition</b> – Bridge is closed to traffic
0	<b>Failed Condition</b> – Bridge is out of service and beyond corrective action

Last Inspection was conducted on April 10, 2003.

Unit Number	NBI RATINGS			
	1	2	3	4
Structure Type	Steel Girder	Steel Truss	Steel Bascule (Lift Span)	Concrete Girder
Length in feet	403.5	1154.9	127.0	222.4
% Of Total Length	21%	60%	7%	12%
 <b>Deck</b>	4 (Poor)	3 (Serious)	4 (Poor)	5 (Fair)
 <b>Superstructure</b>	5 (Fair)	5 (Fair)	4 (Poor)	5 (Fair)
 <b>Substructure</b>	4 (Poor)	4 (Poor)	5 (Fair)	5 (Fair)